

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Salvage Yard

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD086510005</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Douglas Aircraft Co. 190th &amp; Normandie Torrance, CA 90502</b>				A.State Manifest Document Number <b>84924195</b>		B.State Generator's ID			
4. Generator's Phone ( <b>213-533-6677</b> )		6. US EPA ID Number <b>CAD000057760</b>		C.State Transporter's ID <b>62852</b>		D.Transporter's Phone <b>213-830-1720</b>			
5. Transporter 1 Company Name <b>IT Coporation</b>		8. US EPA ID Number		E.State Transporter's		F.Transporter's Phone			
7. Transporter 2 Company Name		10. US EPA ID Number <b>CAD020748125</b>		G.State Facility's ID <b>CAD020748125</b>		H.Facility's Phone			
9. Designated Facility Name and Site Address <b>CASMALIA P.O. Box E NTU Reed Casmalia,,Ca. 93429</b>				12.Containers No. Type		13. Total Quantity		14. Unit Wt/Vol	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				1. Waste Polychlorinated Biphenyls <del>Waste xxx Hazardous solid</del> ORM-E UN2315 (RQ - 10/4.54)		2200		P	
				2. Waste Polychlorinated Biphenyls <del>Waste xxx Hazardous solid</del> ORM-E UN2315 (RQ - 10/4.54)		400		P	
J. Additional Descriptions for Materials Listed Above				K.Handling Codes for Wastes Listed Above					
A. Transformer carcass drained & flushed & residue absorbed with vermiculite.				03					
B. 2 drums contaminated clothing/rags/debris/hand pump									
15. Special Handling Instructions and Additional Information <b>Handle with extreme care. Use NIOSH and OSHA approved safety equipment when handling. Follow emergency contingency plan. PERMIT EH 3-8432</b>									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.									
Printed/Typed Name <b>Donald C. Gerber</b>				Signature <i>Donald C. Gerber</i>				Date <b>12/18/85</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name <b>CRUZ GUTIERREZ SA</b>				Signature <i>CRUZ GUTIERREZ SA</i>	
								Date <b>12/18/85</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name				Signature	
								Date	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name <b>Casmalia Resource Recovery</b>				Signature <i>Marie Cook</i>				Date <b>12/19/85</b>	



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address		Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502		A.State Manifest Document Number 84924195		
4. Generator's Phone (213-533-6677)		6. US EPA ID Number		B.State Generator's ID		
5. Transporter 1 Company Name IT Coproration		7. US EPA ID Number		C.State Transporter's ID		
7. Transporter 2 Company Name		8. US EPA ID Number		D.Transporter's Phone		
9. Designated Facility Name and Site Address CASMALIA P.O. Box E NTU Reed Casmalia, Ca. 93429		10. US EPA ID Number		E.State Transporter's Phone		
				F.Transporter's Phone		
				G.State Facility's ID		
				H.Facility's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste-Polychlorinated Biphenyls, ORM-E UN2315		1	CM	2200	P	261
b. Waste-Polychlorinated Biphenyls, ORM-E UN2315		2	DM	400	P	261
c.						
d.						
J. Additional Descriptions for Materials Listed Above		K.Handling Codes for Wastes Listed Above				
A. Transformer carcas drained & flushed & residue absorbed with vermiculite.						
B. 2 drums contaminated clothing/rags/debris/hand pump						
15. Special Handling Instructions and Additional Information						
Handle with extreme care. Use NIOSH and OSHA approved safety equipment when handling. Follow emergency contingency plan. PERMIT EH 3-8432						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name		Signature		Date		
Donald C. Gerber				Month Day Year 12 18 85		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
Antonio C. Huerto				Month Day Year 12 18 85		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
				Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Date		
SCANNED				Month Day Year		